State of Oregon Drinking Water Program Monthly Disinfection Report for Ground Water Systems

System Name Idaho Power- Oxbow Village PWS ID# 4 1 00384							
EP-B, Entry Point for Month/Year April/2021 Entry Point: Copperfield Park Well Required Minimum Residual 0.2 mg/L							
Date	Time	Source(s) in use		Lowest free chlorine residual at entry point to distribution system (mg/l			
1	0745	Booster Pump		.25		House 565 .15	
2	0700	Booster Pump		.28	1,0000000		
3	0845	Booster Pump		.21			
4	1500	Booster Pump		.20			
5	0615	Booster Pump		.21	House 561	House 5613 .14	
6	0720	Booster Pump		.22			
7	0700	Booster Pump		.21			
8	0630	Booster Pump		.24	House 851 .12		
9	0700	Booster Pump		.25			
10	1800	Booster Pump		,20			
11	1000	Booster Pump		.20			
12	0700	Booster Pump		.23	House 5620 .15		
13	0740	Booster Pump		.24			
14	0746	Booster Pump		.21			
15	0700	Booster Pump		.20	House 565.16		
16	0800	Booster Pump		.21			
17	1545	Booster Pump		.21			
18	0700	Booster Pump		.22			
19	0700	Booster Pump		.20	House 5613	3.13	
20	0700	Booster Pump		.23			
21	0700	Booster Pump		.30			
22	0700	Booster Pump		.22	House 851.15		
23	0720	Booster Pump		.20			
24 25	0700 0720	Booster Pump		.20			
26	0720	Booster Pump		.21			
27	0700	Booster Pump		.21	House 5620.14		
28	0700	Booster Pump Booster Pump		.22			
29	0800	Booster Pump		.21 .23	Haves FOE	4F	
30	0700	Booster Pump		.22	House 565 .15		
31	0700	Booster Pump		.22			
and the second s							
Was the chlorine residual ever less than the required minimum residual of 0.2 mg/L? Yes No If yes, what was the longest time period until the required level was restored? hours							
GWS Serving 3,300 or Fewer GWS Serving More Than 3,300							
	_						
If yes, did you monitor every four hours until the residual returned to 0.2 mg/L? ☐ Yes ☐ No Attach those results and submit them with			reporting month? Yes No		Date continuous monitoring equipment failed:		
			If yes, were grab samples collected every four hours until the / /				
			continuous monitoring equipment was returned to service?		Date it was returned to		
this form.			Yes No service:				
Attach grab sample results and submit them with this form. / /							
Printed N	ame: Tim Fe	erguson	Title: Field Engineer		Operator Certification #:		
Signature	: 13		Phone #: (541) 785-7293		OR		
Date: 05	/ 05 / 2021				Small Groundwater System ⊠		